

#### **Approved Gyratory Compactors**



Pine AFGC125X



Pine AFG1



Brovold



Rainhart



Troxler 4140




Troxler 4141





Interlaken





**IPC ServoPac** 















## Maine DOT

Since going to internal angle set by DAV

In 2002
 Out of over 2000 bulk splits (DOT/Contractor)
 1.5% dispute rate
 0.5% overturned




### Maryland SHA Round Robin - Original



### Maryland SHA Round Robin - DAV

SGC Set to 1.16+0.02 degrees using DAV 12.5mm Mixture / 6 Replicates



# LESSONS LEARNED WITH DAV

#### Gyratory Compactor

- Bearings excessive wear
- Brake not functioning properly;
  does not maintain the same starting point
- Ram head excessive wear
- Column lack of grease
- Machine not maintained; stops during compaction; worn parts need replaced



# LESSONS LEARNED WITH DAV

#### Molds

- $\varkappa$  Out of round
- Excessive wear
- Lack of maintenance



# LESSONS LEARNED WITH DAV

Mix

Z Different mix sizes change internal angle

 Some compactors do not compare; reason is unknown

#### **Refinement of AASHTO T 312-01**

## **Additional Issues**


Implementation Issues:

- ∠ Cost(s)
- Maintenance
- $\varkappa$  Specifications

Mixture stiffness versus internal angle

Mold Wear

Round-robin (inter-laboratory) study



## 2003 IN MARYLAND

#### Gyratory Compactor

Must be serviced and Internal Angle set

*⊾* at 1.16

- Molds must be checked for:
  - ✓ Out of round
  - Excessive wear

